

Step 7: Place stand inside the enclosure
(Front end first)



Step 8: Guide cables through back opening



Step 9: Plug in USB power cable
to a 5V, 2A adapter



Done!



For more information please visit :
<http://wdlabs.wd.com>




WD PiDrive Kit




Enclosure Set Up

Step 1: Insert HDMI connector, then attach cables



Step 2: Place Raspberry Pi on stand




Position small cable behind HDMI connector


Step 3: Place WD PiDrive on stand



Step 4: Bend the PiDrive Cable to form a curve. This will help it fit in the enclosure.



Step 5: Insert microSD™ card



Step 6: Attach USB peripherals (not included)

